

## WELDING PROCEDURE **SPECIFICATION**

WPS - 2007-FOSC-8-A **REV. NO.:** 0 **DATE:** 4/22/2010 \*\*APPLICABILITY\*\*

WELDING PROCESS: GTAW-P-A and ASME: X AWS: OTHER:

**SUPPORTING PQR:** FCS-4 Helium

JOINT: This WPS shall be used in conjunction with the General Welding Standards (GWS) and Welding Fabrication Procedure (WFP) sections and criteria for joint details, repairs, NDE, inspection etc.

Weld Joint Type: Square Butt **Full Penetration** Class: See GWS 1-06 and WFP's for joint details Preparation: Faced square and cleaned N/A **Backing:** Gas **Root Opening:** Gas **Backgrind root:** N/A **Backing Mat.: GTAW Flux:** N/A **Bkgrd Method:** N/A **Backing Retainer:** N/A N/A **FILLER METALS:** Class: and N/A N/A and N/A A No: N/A **SFA Class:** N/A and N/A **Size:** .035 F No:

**Insert:** N/A Insert Desc.: N/A Weld Metal Thickness Ranges:

Flux: Type: N/A Size: N/A thru **AWS Root Pass:** 

Filler Metal Note: **AWS Balance:** thru

**ASME Root Pass:** 0.062 thru 0.150 **ASME Balance:** 0.062 thru 0.150

P/S No. 8 BASE MATERIAL Gr No. 1 to: P/S No. 8 Gr No. 1

Spec. ASTM A312 Type 316L to: Spec. ASTM A312 Type 316L **Grade:** Grade:

AWS: 0 Qualified Pipe Dia. Range: ≥ **ASME:** 

**Qualified Thickness Range: AWS:** thru **ASME:** 0.062 thru 0.150

**OUALIFIED POSITIONS:** AWS: ASME: All Vert. Prog.: N/A

Preheat Min. Temp.: 50°F **GAS: Shielding:** Helium or Gas Composition: 100 / % **Interpass Max. Temp.:** N/A°F / % N/A°F 25 45

to

Gas Flow Rate cfh: **Preheat Maintenance:** to PWHT: Time @ °F Temp. N/A **Backing Gas/Comp:** Helium 100 %

Temp. Range: N/A°F **Backing Gas Flow cfh:** 1 to 1 N/A °F Trailing Gas/Comp: N/A 0 % to

**APPROVAL:** Signatures on file at ENG DATE: 4/22/2010

Monday, June 07, 2010 Page 1 of 2

WPS NO: 2007-FOSC-8-A

WELDING CHARACTERISTICS:

Current: DCEN and Tungsten Type: EWTh-2 Transfer Mode: N/A

Ranges: Amps 50 to 130 Tungsten Dia.: 0.093 Pulsing Cycle: 1.2 to

Volts 11 to 15 Background Current: 40%

Fuel Gas: N/A Flame: N/A Braze temp. °F N/A to N/A

WELDING TECHNIQUE: For fabrication specific requirements such as fittup, cleaning, grinding, PWHT and

inspection criteria refer to Volume 2, Welding Fabrication Procedures

Technique: Automatic Cleaning Method: Wipe with solvent

Single Pass or Multi Pass: S Stringer or Weave bead (S/W): S or S Oscillation: N

GMAW Gun Angle °: to Forehand or Backhand for GMAW (F/B): N/A

No Pass >1/2": True GMAW/FCAW Tube to work distance: N/A

Maximum K/J Heat Input: N/A Travel speed: 6 ipm Gas Cup Size: N/A

PROCEDURE QUALIFIED FOR:

Charpy "V" Notch: N/A Nil-Ductil Transition Temperature: N/A Dynamic Tear: N/A

**Comments:** This WPS was qualified for Pu Oxide Storage containers in a Glovebox.

1) All welding is performed in a Helium atmosphere inside a glove-box.

Weld Layer	Manual Process	Filler Metals	Size	Amp Range	Volt Range	Travel/ipm	Nozzle Angle	Other
1	GTAW-P-A	N/A	.035	50 <b>to</b> 130	11 <b>to</b> 15	4 <b>to</b> 6	to	
2		N/A		to	to	to		
3		N/A		to	to	to		
4		N/A		to	to	to		

REM. \* Weld layers are representative only - actual number of passes and layer sequence may vary.

ML-1/2 projects or jobs must determine if the supporting documentation for this WPS complies with quality requirements of the project/job.

Use of LANL Welding Procedures and Welder Qualifications for non-LANL work shall be at the sole risk and responsibility of the Subcontractor, and the Subcontractor shall indemnify and save LANL and the Government harmless from any and all claims, demands, actions or causes of action, and for any expense or loss by reason of Subcontractor's and their employees posession and use of LANL procedures and qualifications.

Monday, June 07, 2010 Page 2 of 2